





RC10 Firmware Updater

RADIODETECTION 

Installing the application

- Install the updater application by running setup.exe. Administrator privileges required.
- Once installed, the application should appear in the start menu or on the desktop



Using the application

- Open the application from the start menu.
- Connect the target locator to the PC with a USB C cable.
- Switch on the locator whilst holding down the  and  keys.
- The locator will boot into the USB1 App.
- The console window will show "RD8200 USB Device Connected". If no connection can be established, please contact Ken Wright for US based customers at ken.wright@spx.com or Phil Hembery for non-US customers at phil.hembery@spx.com.
- Press any key to start the download process.
- When the process is complete the console window will show "Download Complete"

Checking the update

- Remove the USB cable and press power key to switch on the locator.
- Press power key again to go to menu, use up arrow key to navigate to INFO, then using right and up arrows, navigate to REV.
- REV should read "010"

Troubleshooting

- If no connection can be established, please follow these steps:
 1. Uninstall the Updater
 2. Download the Update [here](#) and reinstall (this is an updated version)
- The locator must be in USB mode for the updater to work. The locator will display the alternating USB/TEST splash screen.
- If the display shows COMM1, power off and ensure both  and  keys are pressed along with power key.